BOREWELL CERTIFICATE

NAME OF WORK: Drillign of borewell and Providing Pumping maintanance and pipeline for supply of water to Chikkasandra abbigere Kammagondanahalli in Ward no.12 in SSD

JOB NO : 012-12-000048

BR : 291/30.8.2013

Work Order No.:EE/DD/Wo/241/12-13 Dt:28.11.2012

The inspection Team deployed for this purpose has opined that

Generally the work executed is satisfactory(in the report available in the file. As such, compliance of Geological Survey report, Yield test report and Water potability test report at this stage is not feasible, since this work was executed **2** years back.

Executive Engineer
Dasarahalli Division
Bruhat Bangalore Mahanagar Palike